



A medical manufacturing facility in Wheeling, IL needed cooling equipment for workers and the manufacturing process. About a dozen units were placed throughout the manufacturing floor. Spot Coolers were necessary for some of the hot workers. Spot Coolers were also necessary for some of the processes. When temperatures get out of hand in manufacturing areas, machines can act up and not produce parts within acceptable tolerances. Therefore, part rejection rates increase, justifying the need for portable spot cooling. If we can help with your any of your manufacturing facility cooling issues, please do not hesitate to give "Rent AC" a call.