



A temporary space in Bloomingdale, IL was being leased in a vacant mall space for job position screening by an employer. When the temperatures started to rise, it was noticed that the roof top unit was not working properly so they phoned a mechanical contractor to service the unit. After the contractor diagnosed the situation, it was determined that a new part was needed to correct the RTU situation. The lead time for the replacement part was 1 to 2 weeks. The customer picked up the phone and called "Rent AC" for temporary equipment. The customer was aware of our exceptional jump on the situation quick service. We arrived within 1 hour with equipment options on our truck. We hooked up some air-cooled portable spot coolers in strategic locations where interviews were taking place as well as water-cooled units. If you have a 911 emergency cooling situation for cooling, please do not hesitate to give us a call. We try to be proactive and overload our trucks with additional equipment for spur-of-the-moment situations. We treat our customers the same way we would like to be treated.